

**Flood Control Project Maintenance
Levee Inspections**

2018 Channel Summary Report

Overall Unit and Item Ratings

Placer County

Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance
Unit Cover Sheet
2018 Channel Inspection Results

Placer County

Channel
Truckee River

Channel Rating	A
Date of Inspection	6/22/2018
DWR Inspector	Zach Jojola
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Hwy 89 / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH_2018_NA0045_13_11_20180823_00028.jpg



View of the river from Highway 89, looking upstream towards the outlet structure. Summer 2018.

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			

Photo 2 of 3 : CH_2018_NA0045_13_11_20180529_00001.jpg



View of the river from Highway 89, looking upstream towards the outlet structure. Summer 2017.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View				
Hwy 89 / Up (cont)				
Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 3 of 3 : CH_2018_NA0045_13_11_20180529_00002.jpg



View of the river from Highway 89 looking upstream towards the outlet structure. Summer 2016.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_13			
Action/Comments				
Inspector Comments: No erosion appeared to be encroaching into the channel bank.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Hwy 89 / Up (cont)

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			
Action/Comments				
Inspector Comments: Monitor scouring of revetment on the slope of the left bank.				

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			

Photo 1 of 6 : CH_2018_NA0045_13_14_20180823_00024.jpg



View of revetment scour just upstream of the dam. Summer 2018.

Photo 2 of 6 : CH_2018_NA0045_13_14_20180823_00026.jpg



Additional view of scouring on the left bank. Summer 2018.

Photo 3 of 6 : CH_2018_NA0045_13_14_20180823_00027.jpg



View of the right bank just upstream of the dam. Summer 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Hwy 89 / Up (cont)

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			
Action/Comments				
Inspector Comments: Monitor scouring of revetment on the slope of the left bank.				

Photo 4 of 6 : CH_2018_NA0045_13_14_20180529_00003.jpg



View of revetment scouring on left bank of the Truckee River. Summer 2017.

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			

Photo 5 of 6 : CH_2018_NA0045_13_14_20180529_00004.jpg



Another view of the revetment scouring. Summer 2017.

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			

Photo 6 of 6 : CH_2018_NA0045_13_14_20180529_00005.jpg



Revetments are starting to show signs of scouring. Monitor revetments. Summer 2016.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Hwy 89 / Up (cont)

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View

Hwy 89 / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH_2018_NA0045_13_16_20180823_00022.jpg



Looking downstream on the Truckee River from Highway 89. Summer 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Hwy 89 / Down (cont)

Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 2 of 3 : CH_2018_NA0045_13_16_20180529_00006.jpg



Looking downstream on the Truckee River from Highway 89. Summer 2017.

Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			

Photo 3 of 3 : CH_2018_NA0045_13_16_20180529_00007.jpg



View of the river looking downstream from Highway. Summer 2016.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_17			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

<

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_19			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

bike bridge / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_21			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 3 : CH_2018_NA0045_13_21_20180823_00021.jpg



View of the Truckee River, looking upstream from the bike bridge. Summer 2018.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_21			

Photo 2 of 3 : CH_2018_NA0045_13_21_20180529_00008.jpg



View of the Truckee River, looking upstream from the bike bridge. Summer 2017.

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_21			

Photo 3 of 3 : CH_2018_NA0045_13_21_20180529_00009.jpg



View of the river looking upstream from the bike bridge. Summer 2016.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

bike bridge / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_23			
Action/Comments				

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_24			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

bike bridge / Up (cont)

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_25			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

bike bridge / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 3 : CH_2018_NA0045_13_26_20180823_00020.jpg



View of the Truckee River, looking downstream from the bike bridge.
Summer 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

bike bridge / Down (cont)

Rating **	A	Issue No.	26 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 2 of 3 : CH_2018_NA0045_13_26_20180529_00010.jpg



View of the Truckee River, looking downstream from the bike bridge. Summer 2017.

Rating **	A	Issue No.	26 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			

Photo 3 of 3 : CH_2018_NA0045_13_26_20180529_00011.jpg



View of the river looking down from the bike bridge. Summer 2016.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

bike bridge / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_28			
Action/Comments				

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_29			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 4 : CH_2018_NA0045_13_31_20180823_00019.jpg



View of the Truckee River, looking upstream from the Tahoe City Lumber Yard. Summer 2018.

Photo 2 of 4 : CH_2018_NA0045_13_31_20180529_00012.jpg



View of the Truckee River, looking upstream from the Tahoe City Lumber Yard. Summer 2017.

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Up (cont)

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 3 of 4 : CH_2018_NA0045_13_31_20180529_00013.jpg



View of the river looking upstream from Tahoe City Lumber Yard. Summer 2016.

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			

Photo 4 of 4 : CH_2018_NA0045_13_31_20180529_00014.jpg



View of the river looking upstream from Tahoe City Lumber Yard. Summer 2016.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_32			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Up (cont)

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_33			
Action/Comments				
Inspector Comments: No erosion appeared to be encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_34			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 4 : CH_2018_NA0045_13_36_20180823_00018.jpg



View of the Truckee River, looking downstream from the Tahoe City Lumber Yard. Summer 2018.

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Photo 2 of 4 : CH_2018_NA0045_13_36_20180529_00015.jpg



View of the Truckee River, looking downstream from the Tahoe City Lumber Yard. Summer 2017.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Down (cont)

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 3 of 4 : CH_2018_NA0045_13_36_20180529_00016.jpg



View of the river looking downstream from Tahoe City Lumber Yard.
Summer 2016.

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Photo 4 of 4 : CH_2018_NA0045_13_36_20180529_00017.jpg



View of the river looking downstream from Tahoe City Lumber Yard.
Summer 2016.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	06/22/2018 06/22/2018	Zach Jojola

Check Point / View

Tahoe City lumber yard / Down (cont)

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_38			
Action/Comments				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement